

**Draft Final Remedial Investigation Report
Former Magna Metals Site**

TABLE OF CONTENTS

Section	Title	Page No.
1.0	INTRODUCTION.....	1-1
1.1	Purpose and Objective	1-1
1.2	Site Background.....	1-1
1.2.1	Site Location and Description.....	1-1
1.2.2	WCHD Department of Health and NYSDEC Sampling History	1-1
1.3	RI Activity Chronological Summary	1-3
2.0	SCOPE OF INVESTIGATION	2-1
2.1	Introduction.....	2-1
2.2	Pit Location Survey.....	2-1
2.2.1	Geophysical Survey	2-3
2.3	Holding Tank/Septic Tank/Leaching Pit/Refuse Area Sampling	2-3
2.4	Surface Water and Sediment Sampling	2-4
2.5	Surface Soil Sampling.....	2-5
2.6	Subsurface Soil Sampling.....	2-6
2.7	Monitoring Well Installation.....	2-6
2.8	Groundwater Contamination Delineation.....	2-8
2.9	Hydraulic Conductivity Testing.....	2-9
2.10	Homeowner Survey	2-9
2.11	Monitoring Well Survey	2-9
2.12	Groundwater Level Measurements and Surface Water Survey	2-10
2.13	Building Interior Sampling	2-10
2.14	Investigation Derived Waste.....	2-10
2.15	Soil Vapor Survey (2006)	2-10
2.16	AKRF Vapor Intrusion Assessment (2007).....	2-11
3.0	PHYSICAL CHARACTERISTICS OF THE STUDY AREA.....	3-1
3.1	Site Geology.....	3-1
3.2	Site Hydrology	3-1
3.3	Cross Section	3-2
4.0	ENVIRONMENTAL SAMPLING RESULTS	4-1
4.1	Introduction.....	4-1
4.2	Holding Tank/Septic Tank/Leaching Pit Analytical Results	4-1
4.2.1	1998 RI/FS	4-1
4.2.2	2004 Supplemental RI.....	4-2
4.3	Refuse Area Analytical Results	4-3
4.3.1	2004 Supplemental RI.....	4-3
4.4	Surface Water Analytical Results	4-3
4.4.1	1998 RI/FS	4-3
4.5	Sediment Analytical Results	4-4
4.5.1	1998 RI/FS	4-4
4.5.2	2004 Supplemental RI.....	4-6
4.6	Surface Soil Analytical Results	4-6

**Draft Final Remedial Investigation Report
Former Magna Metals Site**

TABLE OF CONTENTS (Cont'd)

Section	Title	Page No.
4.6.1	1998 RI/FS	4-6
4.6.2	2004 Supplemental RI.....	4-7
4.7	Subsurface Soil Analytical Results.....	4-7
4.7.1	1998 RI/FS	4-7
4.8	Groundwater Analytical Results.....	4-9
4.8.1	1998 RI/FS	4-9
4.8.2	2004 Supplemental RI.....	4-9
4.8.3	2006 Additional Data Findings.....	4-10
4.9	Soil Gas (2006)	4-10
4.10	AKRF 2007 Subslab Vapor and Indoor Air Results.....	4-11
5.0	HABITAT BASED ASSESSMENTS.....	5-1
5.1	Fish and Wildlife Resources and Environmental Setting (Step I)	5-1
5.1.1	Description of Fish and Wildlife Resources	5-1
5.1.2	Endangered and Threatened Species	5-7
5.1.3	Observations of Stress.....	5-7
5.1.4	Description of Fish and Wildlife Resource Value	5-7
5.1.5	Identification of Applicable Fish and Wildlife Regulatory Criteria.....	5-8
5.2	Pathway Analysis (Step II)	5-9
5.3	Criteria Specific Analysis (Step IIA)	5-10
5.3.1	Surface Water Evaluation	5-11
5.3.2	Sediment Evaluation	5-12
5.3.3	Surface Soil Evaluation.....	5-14
5.4	Analysis of Toxic Effects (Step IIB)	5-15
5.4.1	Areas of Concern for Ecological Receptors.....	5-15
5.4.2	Sampling Station Locations	5-16
5.4.3	Analytical Sampling.....	5-18
5.4.4	Surface Water Toxicity Tests.....	5-18
5.4.5	Sediment Toxicity Tests	5-18
5.4.6	Macroinvertebrate Benthic Survey	5-19
5.4.7	Water Quality and Benthic Substrate Descriptions	5-20
5.5	Data Analysis and Interpretation	5-21
5.5.1	Surface Water Screening.....	5-21
5.5.2	Sediment Screening	5-23
5.5.3	Macroinvertebrate Benthic Survey	5-26
5.5.4	Surface Water Toxicity Tests.....	5-29
5.5.5	Sediment Toxicity Tests	5-30
5.6	Summary of Fish and Wildlife Impact Analysis.....	5-32
5.6.1	Fish and Wildlife Resources and Environmental Setting (Step I)	5-32
5.6.2	Pathway Analysis and Criteria Specific Analysis (Steps IIA and IIB).....	5-33
5.6.3	Toxic Effects Analysis (Step IIC).....	5-33
5.7	Conclusions.....	5-34
5.7.1	Site-Specific Preliminary Remedial Goal Development (PRG).....	5-35

**Draft Final Remedial Investigation Report
Former Magna Metals Site**

TABLE OF CONTENTS (Cont'd)

Section	Title	Page No.
6.0	SUMMARY AND CONCLUSIONS	6-1
6.1	1998 RI/FS Summary	6-1
6.2	2004 Supplemental RI Summary	6-2
6.3	2006 Data Findings	6-3
6.4	2007 AKRF Soil Vapor and Indoor Air Investigation Findings.....	6-4
6.5	RI Completion.....	6-4
7.0	REFERENCES.....	7-1

LIST OF TABLES

Table 1-1	Westchester County Department of Health Water Pollution Investigation on 10/3/78
Table 1-2	Metals Analyses from Westchester County Department of Health Water Pollution Investigation Soils and Bottom Sediment Sampling on 10/13/78
Table 1-3	Metal Analyses from Westchester County Department of Health and New York State Department of Environmental Conservation Core Sampling Below (West of) Former Outflow/Overflow Area (Last Leaching Pit) on 12/15/78
Table 1-4	New York State Department of Environmental Conservation EP Toxicity Extracts Taken on 8/19/82 and 11/16/82, Respectively
Table 1-5	Metals Analyses from Westchester County Health Department Water Pollution Investigation on 2/1/83 and 2/2/83
Table 1-6	Volatile Organic Analyses from Westchester County Health Department Water Pollution Investigation on 2/1/83 and 2/2/83
Table 1-7	Volatile Analyses from Westchester County Health Department Water Pollution Investigation on 3/15/83
Table 1-8	Summary of Total Metal Analyses from NYSDEC Surface Water Sampling on 5/15/84
Table 1-9	Summary of Total Metal Analyses from NYSDEC Sediment/Sludge Sampling on 5/15/84
Table 1-10	New York State Department of Environmental Conservation Division of Environmental Enforcement EP Toxicity Extracts of 5/15/84
Table 1-11	Summary of Volatile Organic Analyses from NYSDEC Surface Water Sampling on 5/15/84
Table 1-12	Summary of Volatile Organic Analyses from NYSDEC Sediment/Sludge Sampling on 5/15/84
Table 2-1	Leach/Septic Pit IDs, Sludge Thickness, and Construction Details
Table 2-2	Groundwater and Surface Water Elevations – March 30, 2004
Table 4-1	Summary of Detected Constituents Holding Tank/Septic Tank/Leaching Pit Analytical Results
Table 4-2	Leach Pit/Refuse Area Samples – Compounds Exceeding Soil Cleanup Criteria
Table 4-3	Summary of Detected Constituents – Surface Water Analytical Results

**Draft Final Remedial Investigation Report
Former Magna Metals Site**

LIST OF TABLES (Cont'd)

Table 4-4	Surface Water Samples – Compounds Exceeding Surface Water Criteria
Table 4-5	Summary of Detected Constituents – Sediment Analytical Results
Table 4-6A	Sediment Samples – PAH Compounds Exceeding Sediment Criteria
Table 4-6B	Sediment Samples – Inorganic Compounds Exceeding Sediment Criteria
Table 4-7	Summary of Detected Constituents – Surface Soil Analytical Results
Table 4-8	Surface Soil Samples – Compounds Exceeding Soil Cleanup Criteria
Table 4-9	Summary of Detected Constituents – Subsurface Soil Analytical Results
Table 4-10	Summary of Detected Constituents – Groundwater Analytical Results
Table 4-11	Groundwater Samples – Compounds Exceeding Groundwater Criteria
Table 4-12	Detected Volatile Organic Compounds for Groundwater Samples – February 2006
Table 4-13	Detected Volatile Organic Compounds for Soil Vapor Samples
Table 4-14	Soil Vapor Analytical Results
Table 5-1	Wildlife Species Observed in the Magna Metals Site Study Area
Table 5-2	Surface Water Screening Assessment – Furnace Brook
Table 5-3	Surface Water Screening Assessment – SVOC Results – Furnace Brook
Table 5-4	Surface Water Screening Assessment – Metals Results – Furnace Brook
Table 5-5	Sediment Screening Assessment – VOC Results – Furnace Brook
Table 5-6	Sediment Screening Assessment – SVOC Results – Furnace Brook
Table 5-7	Sediment Screening Assessment – Pesticide and PCBs Results – Furnace Brook
Table 5-8	Sediment Screening Assessment – Metals Results – Furnace Brook
Table 5-9	Surface Soil Screening Assessment – SVOC Results – Furnace Brook
Table 5-10	Surface Soil Assessment Pesticide and PCB Results
Table 5-11	Surface Soil Assessment Metals Results
Table 5-12	Water Quality Parameters
Table 5-13	Benthic Substrate Characteristics
Table 5-14	Surface Water Screening Assessment – Furnace Brook
Table 5-15	Surface Water Screening Assessment – Unnamed Tributary of Furnace Brook
Table 5-16	Surface Water Screening Assessment – Wetland South of the Unnamed Tributary of Furnace Brook
Table 5-17	Surface Water Screening Assessment – Wetland North of the Unnamed Tributary of Furnace Brook
Table 5-18	Sediment Screening Assessment – Furnace Brook
Table 5-19	Sediment Screening Assessment – Unnamed Tributary
Table 5-20	Sediment Screening Assessment – South Wetland
Table 5-21	Sediment Screening Assessment – Unnamed Pond
Table 5-22	Sediment Screening Assessment – Furnace Brook Below Unnamed Pond
Table 5-23	Benthic Macroinvertebrates Collected from the Magna Metals Site by Tetra Tech EC
Table 5-24	Benthic Macroinvertebrates Collected from the Magna Metals Site by Tetra Tech EC
Table 5-25	Benthic Macroinvertebrates Collected from the Magna Metals Site by Tetra Tech EC

**Draft Final Remedial Investigation Report
Former Magna Metals Site**

LIST OF TABLES (Cont'd)

- | | |
|------------|--|
| Table 5-26 | Benthic Macroinvertebrates Collected from the Magna Metals Site by Tetra Tech EC |
| Table 5-27 | Benthic Macroinvertebrates Collected from the Magna Metals Site by Tetra Tech EC |
| Table 5-28 | Benthic Macroinvertebrates Collected from the Magna Metals Site by Tetra Tech EC |
| Table 5-29 | Benthic Macroinvertebrates Collected from the Magna Metals Site by Tetra Tech EC |
| Table 5-30 | Biometrics for Benthics |
| Table 5-31 | Ceriodaphnia dubia Surface Water Toxicity Results |
| Table 5-32 | Chironomus tentans and Hyalella azteca Sediment Toxicity Test Results |

LIST OF FIGURES

- | | |
|------------|--|
| Figure 1-1 | Site Location Map |
| Figure 2-1 | Leach Pit Location Map – 1998 RI Summary |
| Figure 2-2 | Site Plan with Sample, Pit and Monitoring Well Locations |
| Figure 2-3 | Leach/Septic Pit Location Map – 2004 Supplemental RI |
| Figure 2-4 | Soil Vapor Samples, Sub-Slab Vapor Sample, and Monitoring Well Locations |
| Figure 2-5 | Sampling Locations |
| Figure 3-1 | Drainage Map – 1998 RI Summary |
| Figure 3-2 | Cross-Section A-A' -2004 Supplemental RI |
| Figure 3-3 | Overburden Groundwater Contours – 2004 Supplemental RI |
| Figure 4-1 | Constituents Detected at Concentrations Exceeding Applicable Criteria Levels – 1998 RI Summary |
| Figure 4-2 | Soil Exceedances – 2004 Supplemental RI |
| Figure 4-3 | Sediment and Surface Water Exceedances – 2004 Supplemental RI |
| Figure 4-4 | Groundwater Exceedances – 2004 Supplemental RI |
| Figure 4-5 | Groundwater Exceedances – February 2006 |
| Figure 4-6 | Detected Constituents in Soil Vapor Samples – January 2006 |
| Figure 5-1 | Documented Fish and Wildlife Resources – 1998 RI Summary |
| Figure 5-2 | Cover Type Map – 1998 RI Summary |
| Figure 5-3 | Sample Station Location Map -- 2004 Supplemental RI |
| Figure 5-4 | Ceriodaphnia dubia Chronic Surface Water Toxicity Test Mean Survival |
| Figure 5-5 | Ceriodaphnia dubia Chronic Surface Water Toxicity Test Mean Reproduction Survival |
| Figure 5-6 | Chironomus tentans 10-Day Whole Sediment Toxicity Test Mean Survival |
| Figure 5-7 | Chironomus tentans 10-Day Whole Sediment Toxicity Test Mean Growth |
| Figure 5-8 | Hyalella azteca 10-Day Whole Sediment Toxicity Test Mean Survival |
| Figure 5-9 | Hyalella azteca 10-Day Whole Sediment Toxicity Test Mean Growth |

**Draft Final Remedial Investigation Report
Former Magna Metals Site**

LIST OF APPENDICES

- Appendix A NYSDEC Historical Documentation
- Appendix B Photograph Log of Leach Pit Excavation Findings
- Appendix C Geophysical Reports
- Appendix D Boring Logs, Well Development Data, Well Purge Sheets and Well Construction Diagrams
- Appendix E Slug Test Data
- Appendix F 1998 RI/FS Data Tabulation
- Appendix G 2004 Summary Sheets for Sampling Results
- Appendix H 2006 Additional Data Finding Report Data Summary Sheets
- Appendix I Laboratory and Toxicity Reports for the Fish and Wildlife Impact Analyses
- Appendix J Data Usability Summary Reports
- Appendix K Indoor Air Questionnaire and Building Inventory